

Firmware 3.34R01



New Release and Update Information

Firmware Core: 3.34R01

Compatible RAIDWatch version: 2.0

Software updates are available at <ftp.infortrend.com.tw/RAIDWatch/2.0>

1. Overview

New features:

No new features added to this revision. See the description below at point 3: *List of Problems Fixed*.

2. Applicable Products

Firmware 3.34R01 is applicable to the following subsystems:

Models	Corresponding Binary
EonStor A08U-G1A3	FA334R01_17_IFT_ESA08UG1A3.zip
EonStor A12U-G1A3	FA334R01_17_IFT_ESA12UG1A3.zip
EonStor A16U-G1A3	FA334R01_15_IFT_ESA16UG1A3.zip

3. List of Problems Fixed

SCSI HBA Scan Failure

Fixed the bug that causes HBAs not being able to detect Infortrend RAID subsystems during the channel scanning process. The problem occurs when using channel 1 to connect to host computers.